


Seat:


Fabrics / Cat.2



156



157




736



737




170



159


Composition: 73% VI - 16% CO - 10% LI - 1% SE
Grade: 2
Cleaning: (P) (X) (X) (X) (X)




666



665




667




668

Seat:

Fabrics / Cat.2



669



734

Composition: 51% CO - 49% PL

Grade: 2

Cleaning: 



670




671




672



673



674




675



735

Seat:

Fabrics / Cat.2



676



642




676



644



645



646



647



648



732



733


Composition: 36% CO - 34% VI - 16% LI - 14% PL
Grade: 2
Cleaning:

Seat:


Fabrics / Cat.2




A01



A02



A03




A04



A05



A06




A07

Composition: 70% VI - 30% LI

Grade: 2


Cleaning:     



A11



A12



A13



A14

Seat:

Fabrics / Cat.2



Composition: 41% VI - 39% PL - 10% LI - 8% CO - 2% PC


Grade: 2

Cleaning:

A15



A51



A52



A53



A54



A55



A56



A57



A58

Seat:

Fabrics / Cat.2



A59



A60

Composition: 100% PL

Grade: 2

Cleaning:     



B21




B22




B23



B24




B25




B26

Seat:

Fabrics / Cat.2



B81



B82




B83




B84




B85



B86



B87



C01



C02



C03



C04

Seat:


Fabrics / Cat.2



C05



C06



C07


Composition: 100% PL

Grade: 2


Cleaning:



C11




C12



C13



C14



C15



C16

Composition: 66% CO - 34% NY

Grade: 2


Cleaning:

Seat:


Fabrics / Cat.2



C21




C22



C23




C24



C25



C26



C27

Composition: 100% CO
Grade: 2
Cleaning:     



C83



C81



C82




C84

Composition: 42% CO - 58% VI
Grade: 2
Cleaning:     

Seat:


Fabrics / Cat.2



C93



C91




C92




C95


Composition: 25% CO - 20% LI - 15% PL - 40% VI
Grade: 2
Cleaning:



D05



D01



D03



C06




C04


Composition: 51% PL - 42% VI - 4% LI - 3% PA
Grade: 2
Cleaning:

Seat:


Fabrics / Cat.2



D17



D11



D12



D13



D14




D15




D16

Composition: 66% PL - 34% VI
Grade: 2
Cleaning: 



D24



D21




D23



D25

Seat:

Fabrics / Cat.2




Composition: 66% CO - 34% PL

Grade: 2

Cleaning:     

D26



D32




D33




D34



D35



D41



D42



D43

Composition: 82% VI - 11% CO - 7% PL

Grade: Extra

Cleaning:    

Seat:

Fabrics / Cat.2



D44



D45



D46

Composition: 45% VI - 28% PC - 11% CO - 10% PL - 6% LI
Grade: 2
Cleaning:



D64




D61



D62



D63



D65



D66




D67


Composition: 43% CO - 57% PL
Grade: 2
Cleaning:

Seat:

Fabrics / Cat.2




D71



D72



D73



D74



D75




D76




D77

Composition: 97% CO - 31% PL
Grade: 2
Cleaning: dry clean




E01



E02



E03




E04

Seat:

Fabrics / Cat.2



E05



E06

Composition: 100% LI

Grade: 2


Cleaning: (P) [iron icon] [30° icon] [X icon] [X icon]



642



644



646



648



676



732



733

Composition: 36% CO - 34% VI - 16% LI - 14% PL
Grade: 2
Cleaning: (P) [iron icon] [X icon] [X icon] [X icon]

Seat:

Fabrics / Cat.2




E11



E12



E13



E14




E15

Composition: 70% CO - 30% VI

Grade: 2


Cleaning:     



E31



E32



E33



E34

Seat:

Fabrics / Cat.2



E35




E36


Composition: 50% PL - 36% VI - 12% LI - 2% SE

Grade: 2

Cleaning: (P)



E41




E42



E43



E44



E45



E46



E47

Composition: 19% VI - 72% CO - 9% LI

Grade: 2


Cleaning: (P)

Seat:

Fabrics / Cat.2



E51



E52



E53



E54



E55



E56



E57



Composition: 41% PC - 36% PL - 14% CO - 6% JU - 3% VI
Grade: 2
Cleaning: 



E91



E92



E93



E94

Seat:

Fabrics / Cat.2



E95



E96



E97

Composition: 30% VI - 40% CO - 10% LI - 10% PL - 10% PC
Grade: 2
Cleaning: 



F01



F02



F03



F04



F05



F06



F07

Composition: 55% VI - 23% CO - 17% PL - 5% PC
Grade: 2
Cleaning: 

Beech Wood Finishes:



Silver Matt



Crystal Black HG



Crystal White HG



Etimoe HG



Natural Matt



Walnut Matt



Crystal Grey HG



Pioma Mahogany Matt



Marocco Matt



5th Avenue HG



Tanganica HG



Ebony HG



Cherry Medium Matt



Wengé Matt



Black Matt



Zulu HG



White HG



Gold Matt



Sand HG



Silk HG